





PROMI

PWT50




16.5.2017

- D** Montageanleitung
- FR** Notice de montage
- NL** Handleiding voor de montage
- CZ** Montážní návod
- HU** Szerelési útmutató
- TR** Montaj talimatı
- GB** Assembly Instructions
- IT** Istruzioni di montaggio
- PL** Instrukcja montażu
- SK** Návod na montáž
- RO** Instrucțiuni de montaj
- RU** Инструкция по монтажу





20 min.

1






NA 4x13 x9	C x20	Z x20	N 3x20 x8	X x14	M M4x22 x1	W3 x1	ZA x1	TB x1
B x20	A 8x32 x20	H 6.3x13 x8	R x4	PC x4	HD x8	NC 4x16 x6	NGD x4	TA x1
							ZD x6	Z x8






2




3






4





5



M 1Mx22 x1	W3 x1
NA 4x13 x1	ZD x1
PC x4	NC 4x16 x6
NA x8	ZD x6





C x4	Z x4
----------------	----------------






C x8	Z x8
----------------	----------------




11





9



10





12



- TB**
x1
- TA**
x1
- Z**
x8

13



- ZA**
x1